



IEC 90-112 H (ca 1-4 kW)



- Reduce energy loss
- Increase availability
- Ensures quality maintenance

With Gemex a change of belts just takes a few minutes. No alignment is necessary on regular service, since the motor is not loosened. Always correct alignment and belt tension gives longer belt, pulley and bearing life- no unnecessary interruptions in the production! Belt tension can be checked and adjusted in no time using the pump and the manometer. Optimized running conditions gives improved efficiency. No special training required – easy handling.

GEMEX IEC 90-112 H

